Dura-Whelp. Pad Care & Instructions

Basic Care

* We recommend washing pads before initial use *

- Machine wash on warm, gentle cycle
- Water temperature should not exceed 120 degrees
- Hang to dry or machine dry on a cool, gentle cycle
- Do not over-dry pad
- Shake to fluff

Initial Installation

- 1. Center pad in whelping box.
- 2. Attach Velcro from the fastener pack to all four corners of the pad.
- 3. Clean the floor of your whelping box using a clean rag and rubbing alcohol, allowing to dry completely.
- 4. Remove the protective film from the adhesive and press firmly onto floor one corner at a time.

